


2012 R/S/L Workshop Presentation

Model Visualization Tools / Techniques

Example 2

Screenshot 1: SO₂ point sources with emissions > 100 tpy from the 2008 v1.5 NEI and source control changes prior to and after 2008




2012 R/S/L Workshop Presentation

Model Visualization Tools / Techniques

Example 2

Screenshot 2: 2009-11 preliminary 1-hr SO₂ design values in Region 3




2012 R/S/L Workshop Presentation

Model Visualization Tools / Techniques

Example 2

Screenshot 3: Close in look at Indiana County, PA




2012 R/S/L Workshop Presentation

Model Visualization Tools / Techniques

Example 2

Screenshot 4: Close in shot of NEI position of the Homer City power plant



2012 R/S/L Workshop Presentation

Model Visualization Tools / Techniques

Example 2

Screenshot 5: Elevation and Johnstown wind rose

